


From: Lytle.Darren@epamail.epa.gov
To: [Robert Hankinson](#)
Subject: Re: Gardner, MA pinhole leaks
Date: Wednesday, May 4, 2011 12:37:27 PM

interesting- have not seen these before. I should also note that we can do biological analysis at some point if things point to that direction-

Darren Lytle, PhD, PE
Chief (acting), Treatment Technology Evaluation Branch
U.S. Environmental Protection Agency
ORD/NRMRL/WSWRD- MS 683
26 W. Martin Luther King Dr.
Cincinnati, Ohio 45268

phone (513) 569-7432
fax (513) 569-7892

 Robert Hankinson ---05/04/2011 12:07:27 PM---Hi Darren, thanks for making time to talk to me today.
Here is a location with a history of coil fa

From: Robert Hankinson <rhankinson@gardner-ma.gov>
To: Darren Lytle/CI/USEPA/US@EPA
Date: 05/04/2011 12:07 PM
Subject: Gardner, MA pinhole leaks

Hi Darren, thanks for making time to talk to me today. Here is a location with a history of coil failures and photos
I will proceed with water samples and coils.
Regards, Bob

Bob Hankinson
City Engineer, Gardner, MA
rhankinson@gardner-ma.gov
(978)-630-4010

[attachment "DSC00502.JPG" deleted by Darren Lytle/CI/USEPA/US] [attachment "DSC00498.JPG" deleted by Darren Lytle/CI/USEPA/US] [attachment "DSC00500.JPG" deleted by Darren Lytle/CI/USEPA/US]